

HST #837181627

DATE 2017-05-04	TECHNICIAN Darren Mann		JOB/O 7259	RDER #	REFERENCE TEXT Client reference
FIRST NAME Aaron		LAST NAME Oye	7		
BILLING ADDRESS COMPANY / BILLING NAME 503 - 522 WEST 8TH AVE VANCOUVER, V5Z0A9 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 503 - 522 WEST 8TH AVE, BUZ LISA(WIFE): 778.999.5709 VANCOUVER, V5Z0A9 BRITISH COLUMBIA, CANADA	
PHONE 778-835-4337				EMAIL aaronoye@outlook.com	

REASON FOR TODAY'S CALL:

Hi, Please see attached photo. When we turn our shower on, water comes from both the shower head and the faucet below. My brother-in-law lives in the same condo building, and has the exact same problem. He would likely get his fixed at the same time as well, if its cheaper to do so. Thanks, Aaron Oye 778-835-4337

DESCRIPTION OF WORK PERFORMED:

---503: I replaced the tub/shower diverter cartridge and tested. ---602: I replaced the tub/shower diverter cartridge and trim plate. Tested and in good working order.

ооо. т терг	acca the tub/s	mower diverter carriage and tested 002. Treplaced the tub/shower diverter carriage and thin plate. Test	sa ana in good wor	mig order.
QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
2		Replace Tub/Shower Diverter - Danze(Taju) - DISCOUNTED	\$109.00	\$218.00
Q.me	(1	eedback warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$218.00
	t our feedbac	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$10.90
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!			TOTAL:	\$228.90
		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED RUSTED DETERIORATION OR LEAD PIPES FLYTURES CLEAN OUTS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE

DATE