

HST #837181627

DATE 2017-05-19	TECHNICIAN Darren Mann		JOB/ORDER # 7303	REFERENCE TEXT Client reference
FIRST NAME Soyoung		LAST NAME Min		
BILLING ADDRESS COMPANY / BILLING NAME 1704 - 1255 SEYMOUR ST VANCOUVER, V6B 0H1 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 1704 - 1255 SEYMOUR STREET BUZZER: 856 VANCOUVER, V6B 0H1 BRITISH COLUMBIA, CANADA	
PHONE 604.379.6987			EMAIL msssong2@gmail.cor	n

REASON FOR TODAY'S CALL:

Cannot change the bathtub spout into the shower head. It's leaking.

DESCRIPTION OF WORK PERFORMED:

The diverter spout was broken internally and could not be repaired. I replaced the diverter spout with new and tested.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1		Replace Standard Tub Spout	Diverter	\$159.00	\$159.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$159.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		\$7.95
		s from your			\$166.95

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

