

(E) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-06-15	TECHNICIAN Darren Mann		JOB/OI 7392	RDER #	REFERENCE TEXT Client reference
FIRST NAME Judi		LAST NAME Trudel	7		
BILLING ADDRESS EMR VACATION RENTALS 106 - 1016 MCCALLUM ROAD VICTORIA, V9B4C6 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 3103 - 602 CITADEL PARADE SAMANTHA: 604.345.2546 VICTORIA, BRITISH COLUMBIA, CANADA	
PHONE 1-866-800-8880	-			EMAIL judi@emrvr.com	

REASON FOR TODAY'S CALL:

-tub spout not diverting water to shower. -shower head will not fit in holder.

DESCRIPTION OF WORK PERFORMED:

-The tub spout was not diverting water to the shower head. I replaced the tub spout with a new Delta pull-down type diverter spout and tested. -The holder for the shower spray head was flipped upside down. I flipped it right side up and it is functioning normally.

QTY .	CODE	DESCRIPTION				UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter				\$159.00	\$159.00
Guve us Geedback page at: Mease visit our feedback page at: Mease visit our feedback page at: Mease visit our feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTE WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS H		SUBTOTAL:	\$159.00	
				IADE, ABSOLUTELY NO	GST (5%):	\$7.95	
		INTEREST A			TOTAL:	\$166.95	
		MATERIALS SETTLED, RI RESULTING					
				CUSTOMER SIGNATURE	DATE		