

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-06-08	TECHNICIAN Darren Mann		JOB/O 7371	RDER #	REFERENCE TEXT Client reference
FIRST NAME Dunowen Properties		LAST NAME Admin	7		
BILLING ADDRESS DUNOWEN PROPERTIES 201 - 1288 ALBERNI STREET VANCOUVER, V6E 4N5 BRITISH COLUMBIA, CANADA		$\sim$	4	SERVICE ADDRESS 2205 - 938 SMITHE ST OCCUPIED VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.736.1900				EMAIL operations@dunowen.com	

REASON FOR TODAY'S CALL:

Shower has no pressure. Shower/tub switch stuck on shower.

## DESCRIPTION OF WORK PERFORMED:

The tub spout was not fully diverting water to the shower head. I replaced the spout with a Delta pull-down type diverter spout and tested. The shower head seems to be getting adequate pressure but it will not switch between spray functions, it is stuck on one of them.

QTY.	CODE			DESCRIPTION	UNIT PRICE	PRICE	
1		Replace Standard	Replace Standard Tub Spout Diverter				\$159.00
Cure of Goodle al			WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE WARRANTY ON CUSTOMER SUPPLIED MATERIALS. IT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDG		SUBTOTAL:	\$159.00
<b>Gwe us Feedback</b> Please visit our feedback page at:			GST (5%):			\$7.95	
www.yaletownplumbing.com/feedback [1] Fill in the required details from your			TOTAL:		\$166.95		
invoice and tell us how we did. <u>Thank You!</u>		MATERIALS SETTLED, R RESULTING	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT R UISTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUT FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. T CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MA E. & O. E.	ESPONSIBLE FOR BROKEN, 'S AND ANY OTHER DAMAGES			
				CUSTOMER SIGNATURE	DATE		