

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-07-04	TECHNICIAN Darren Mann		JOB/ORDER # 7464		REFERENCE TEXT Client reference
FIRST NAME Easyrent		LAST NAME Admin	7		
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 2908 - 928 BEATTY ST SUITE VACANT, KEYS WITH CONCIERGE VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.662.3279				EMAIL info@easyrent.ca	

REASON FOR TODAY'S CALL: tub/shower diverter not working

DESCRIPTION OF WORK PERFORMED:

The tub spout diverter was broken. I replaced the tub spout with a new Delta pull-down type diverter spout and tested. During testing I noticed the shower head was spraying out of the side. I replaced the shower head & arm and tested again.

QTY .	CODE		UNIT PRICE	PRICE	
1		Replace Standard Tub Spout Diverter			\$159.00
1		Delta Shower Head	\$20.00	\$20.00	
Come of Good and			WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$179.00
Give us Feedback Please visit our feedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank Youl</u>			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$8.95
		.com/feedback [1]	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$187.95
			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		
			CUSTOMER SIGNATURE DATE		