

HST #837181627

DATE 2017-07-11	TECHNICIAN Darren Mann		JOB/ORDER # 7490	REFERENCE TEXT Client reference	
FIRST NAME Bill		LAST NAME Lysaght			
BILLING ADDRESS COMPANY / BILLING NAME 5 - 888 WEST 16TH AVE VANCOUVER, V5Z 1T1 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 5 - 888 WEST 16TH AVENUE VANCOUVER, V5Z 1T1 BRITISH COLUMBIA, CANADA		
PHONE 778.994.9092			EMAIL bill.lysaght@hotmai	EMAIL bill.lysaght@hotmail.com	

REASON FOR TODAY'S CALL:

Dual flush push button toilet cistern is not filling properly. After flushing, tank is sometimes not filling properly: Inlet valve/buoy does not open to start filling OR Inlet valve/buoy opens for 2-3 secs and closes with water filling for few secs and turning off continually If helpful, I can provide a photo.

DESCRIPTION OF WORK PERFORMED:

The FillValve was malfunctioning. I replaced the FillValve & supply line and tested.

QTY.	CODE	DESCRIPTION			PRICE
1		Replace toilet FillValve -	standard	\$159.00	\$159.00
Give us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$159.00
LABOUR - 1 YEAR ON N			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$166.95
INTERES			REST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY BE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2017-07-11

CUSTOMER SIGNATURE

DATE