

(a) @SimplyPlumbing f YaletownPlumbing

HST #837181627

DATE 2017-07-14	TECHNICIAN Darren Mann		JOB/ORDER # 7494		REFERENCE TEXT Client reference	
FIRST NAME Robert		LAST NAME MacKie	7			
BILLING ADDRESS COMPANY / BILLING NAME 309 - 1082 SEYMOUR ST VANCOUVER, V6B 1X9 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 309 - 1082 SEYMOUR ST, BUZZER 3030 VANCOUVER, V6B 1X9 BRITISH COLUMBIA, CANADA		
PHONE 604.603.1136				EMAIL robertfmackie@gmail.com		

REASON FOR TODAY'S CALL:

The diverter pull handle has popped out of our tub faucet. We can't seem to get it back in and it just sprays water upwards when the water is turned on.

DESCRIPTION OF WORK PERFORMED:

I replaced the tub spout with a Delta pull-down type diverter spout and tested.

QTY.	CODE			UNIT PRICE	PRICE		
1		Replace Standard	tandard Tub Spout Diverter				\$159.00
Rung of Goodland			WARRANTY: <u>PA</u>	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		SUBTOTAL:	\$159.00
Give us Jeedback page at: <u>www.yaletownplumbing.com/feedback</u> [1] Fill in the required details from your invoice and tell us how we did. <u>Thank You!</u>		LA	BOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOIE		GST (5%):	\$7.95	
		_	ARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$166.95		
		MATERIALS LISTED SETTLED, RUSTED RESULTING FROM	CES LISTED ABOVE ARE SATISFACTORY COMPLETED ANI D HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT I O, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OU CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING ITHE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, N E. CUSTOMER SIGNATURE	RESPONSIBLE FOR BROKEN, TS AND ANY OTHER DAMAGES 5.			