



DATE 2017-07-27	TECHNICIAN Darren Mann	JOB/ORDER # 7544	REFERENCE TEXT Client reference
FIRST NAME Cindy		LAST NAME Khatkar	
BILLING ADDRESS COMPANY / BILLING NAME 911 - 550 TAYLOR ST VANCOUVER, V3B 1R1 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 911 - 550 TAYLOR STREET BUZZER: 0911 VANCOUVER, V3B 1R1 BRITISH COLUMBIA, CANADA	
PHONE 1.206.606.3653		EMAIL cindy_khatkar@hotmail.com	

REASON FOR TODAY'S CALL:
 leaky faucet in the bath tub. Sangmi Min(tenant): (778) 709-0037

DESCRIPTION OF WORK PERFORMED:
 The pressure balance control cartridge was malfunctioning internally, allowing water to trickle through even when the mixing cartridge was set to the off position. I replaced this pressure balance control cartridge and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Shower Piston PB Pressure Balance Control Cartridge	\$169.00	\$169.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$169.00
GST (5%):	\$8.45
TOTAL:	\$177.45

_____ 2017-07-27

 CUSTOMER SIGNATURE DATE