

HST #837181627

DATE 2017-08-17	TECHNICIAN Darren Mann		JOB/ORDER # 7618	REFERENCE TEXT Client reference	
FIRST NAME John		LAST NAME Beatty			
BILLING ADDRESS COMPANY / BILLING NAME 304 - 27 ALEXANDER ST VANCOUVER, V6A 1B2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 304 - 27 ALEXANDER ST BUZ#6 VANCOUVER, V6A 1B2 BRITISH COLUMBIA, CANADA		
PHONE 604.682.5740			EMAIL beatty0007@telus.net) / l	

REASON FOR TODAY'S CALL:

Thank You!

Leaking toilet Appears to be broken seal under bowl at floor Rocking toilet

DESCRIPTION OF WORK PERFORMED:

I noticed a hairline crack on the right sight of the toilet at the base starting from the teebolt hole. I mentioned this to John but he decided to go ahead with the toilet wax seal replacement. I lifted the toilet, cleaned the floor and underside of the toilet, and reinstalled with a new MaxWax wax ring and supply line. Tested and no leaks present.

QTY.	CODE	DESCRIPTION			UNIT PRICE	PRICE
1		Replace Toilet Wax Seal - Standard			\$189.00	\$189.00
Gwe us Feedback WARRANTY:			WARRANTY:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$189.00
Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$9.45	
	www.yaletownplumbing.com/feedback [1] Fill in the required details from your		INTEDEST A	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$198.45
invoice and tell us how we did.		MADE THAT MATERIALS	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, JSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES			

RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

CUSTOMER SIGNATURE

CHARGES. E. & O. E.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

2017-08-17