

Phone: 604.727.4484 yaletownplumbing.com

SimplyPlumbing **F** YaletownPlumbing

HST #837181627

GST (5%):

TOTAL:

\$10.68

\$224.18

DATE 2017-09-20	TECHNICIAN Darren Mann		JOB/ORDER # 7725		REFERENCE TEXT Client reference
FIRST NAME Dustin		LAST NAME Nielsen	7		
BILLING ADDRESS N/A 633 ABBOTT STREET VANCOUVER, V6B0J3 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 307 - 633 ABBOTT ST BUZZER: N/A VANCOUVER, V6B0J3 BRITISH COLUMBIA, CANADA	
PHONE 604-916-6061				EMAIL dunielsen@outlook.com	

REASON FOR TODAY'S CALL:

Tub Shower - Tub spout has detached from faceplate. Flaceplate likely needs to be removed from tiles/pipe to reattach the spout. The shower diverter isn't on the spout, which should make it easier. Small chance a new spout needs to be installed if unable to reattach existing faucet.

## DESCRIPTION OF WORK PERFORMED:

?Sep20: I removed the old spout and installed a brass nipple and cap so the shower can be used until a new spout is sourced. ?Oct5: I installed a new Delta spout and tested.

<b>QTY</b> .	CODE	DESCRIPTION		PRICE
0.5	1.	Labour - Sep20	\$109.00	\$54.50
1		Replace Standard Tub Spout - Delta	\$159.00	\$159.00
0		warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$213.50

WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

Gwe us Feedback

Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.

Thank You!

MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RE SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. <b>TERMS</b> : NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MAT CHARGES. E. & O. E.	AND ANY OTHER DAMAGE
DAT	
	2017-09-20
CUSTOMER SIGNATURE	DATE

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND

MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO