



HST #837181627

| DATE<br>2017-10-13  | TECHNICIAN<br>Darren Mann |                     | JOB/ORDER # 7827 |  | REFERENCE TEXT<br>Client reference |
|---|---------------------------|---------------------|------------------|--|------------------------------------|
| FIRST NAME<br>Maria   |                           | LAST NAME<br>Baljak |                  |  |                                    |
| BILLING ADDRESS COMPANY / BILLING NAME 2635 PRINCE EDWARD ST VANCOUVER, V5T4V7 BRITISH COLUMBIA, CANADA |                           |                     | 4                | #505 - 2635 PRINCE EDWARD ST, BUZZER 062 AARON(TENANT): 778.288.0488 EMAIL@AARONVIDAS.COM VANCOUVER, V5T4V7 BRITISH COLUMBIA, CANADA |                                    |
| PHONE<br>604-831-4100   | _                         |                     |                  | EMAIL<br>sydney91@hotmail.com  |                                    |

REASON FOR TODAY'S CALL: tub/shower diverter not functioning

## DESCRIPTION OF WORK PERFORMED:

I replaced the tub spout with a new Delta pull-down type diverter spout and tested.

| QTY.  | CODE | DESCRIPTION   | UNIT PRICE | PRICE    |  |  |  |  |  |
|---|------|---|------------|----------|--|--|--|--|--|
| 1   |      | Replace Standard Tub Spout Diverter   | \$159.00   | \$159.00 |  |  |  |  |  |
| <i>Q</i>  | (1   | WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY                                  | SUBTOTAL:  | \$159.00 |  |  |  |  |  |
| Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank You! |      | LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF                | GST (5%):  | \$7.95   |  |  |  |  |  |
|   |      |   | TOTAL:     | \$166.95 |  |  |  |  |  |
|   |      | MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, |            |          |  |  |  |  |  |

CUSTOMER SIGNATURE

DATE