



HST #837181627

DATE 2017-10-16	TECHNICIAN Darren Mann		JOB/ORDER # 7830	REFERENCE TEXT Client reference
FIRST NAME Randy		LAST NAME Romero		
BILLING ADDRESS COMPANY / BILLING NAME 708 - 1008 CAMBIE ST VANCOUVER, V6B6J7 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 708 - 1008 CAMBIE BUZZER: 5033 VANCOUVER, V686 BRITISH COLUMBIA	ST SJ7
PHONE 778.386.4140		EMAIL randyjromero@gmail	EMAIL randyjromero@gmail.com	

REASON FOR TODAY'S CALL:

1. The hose (?) for my faucet is broken and is leaking water. Please see picture. 2. My undermount sink needs to re-secured. Please see picture.

DESCRIPTION OF WORK PERFORMED:

-I resecured the kitchen sink using L-brackets and resiliconed. -The kitchen faucet spray head was not properly connected to the spray hose. I tightened this connection and tested. No leaks present.

TECHNICIAN RECOMMENDATIONS:

The garburator has cracks in the housing and should be replaced soon as these cracks will eventually start allowing water to leak out.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Re-Attach/Secure Under-mount Kitchen Sink		\$209.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$209.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback Fill in the required details from your invoice and tell us how we did.		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$10.45
		s from your	TOTAL:	\$219.45
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HERE	BY L	

Thank You!

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

2017-10-16

CUSTOMER SIGNATURE

DATE