



DATE 2017-10-17	TECHNICIAN Darren Mann	JOB/ORDER # 7776	REFERENCE TEXT Client reference
FIRST NAME Scott		LAST NAME Platt	
BILLING ADDRESS COMPANY / BILLING NAME 208 - 1055 RICHARDS ST VANCOUVER, V6C0B2 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 208 - 1055 RICHARDS ST BUZZER: 8195 VANCOUVER, V6C0B2 BRITISH COLUMBIA, CANADA	
PHONE 604.809.5483		EMAIL scottjplatt@gmail.com	

REASON FOR TODAY'S CALL:  
Shower diverter for bathtub is messed up.

DESCRIPTION OF WORK PERFORMED:  
The trim handle was seized onto the stem of the mixing cartridge. I was able to remove the trim but damaged it in the process. I replaced the mixing & pressure balance cartridge, the diverter spool, and installed a new trim and handle. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Quoted Price	\$199.00	\$199.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



2017-10-17

---

CUSTOMER SIGNATURE DATE

SUBTOTAL:	\$199.00
GST (5%):	\$9.95
<b>TOTAL:</b>	<b>\$208.95</b>