



DATE 2017-11-03	TECHNICIAN Darren Mann	JOB/ORDER # 7888	REFERENCE TEXT Client reference
FIRST NAME Ricardo		LAST NAME Rosales	
BILLING ADDRESS COMPANY / BILLING NAME 1707 - 1189 MELVILLE ST VANCOUVER, V6E4T8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1606 - 1331 WEST GEORGIA ST BUZZER: N AOIFE: 604.716.1990 VANCOUVER, V6E4P1 BRITISH COLUMBIA, CANADA	
PHONE 778.386.4399		EMAIL ricardorosev@hotmail.com	

REASON FOR TODAY'S CALL:

1. Shower not enough pressure. Seems to be the diverter. 2. Bathroom sink water stopper loose. *key with concierge

DESCRIPTION OF WORK PERFORMED:

The tub spout was not fully diverting water to the shower head. I replaced this tub spout with a new Delta pull-down type diverter spout and during testing noticed the shower head, with full pressure, was spraying iratically. I replaced the shower head with new and tested again.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00
1		Delta Shower Head	\$20.00	\$20.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$179.00
GST (5%):	\$8.95
TOTAL:	\$187.95

_____ 2017-11-03

 CUSTOMER SIGNATURE DATE