



HST #837181627

DATE 2017-11-15	TECHNICIAN Darren Mann		JOB/ORDER # 7917	REFERENCE TEXT Client reference
FIRST NAME Michael		LAST NAME Duchnych		·
BILLING ADDRESS COMPANY / BILLING NAME 305 - 928 RICHARDS ST VANCOUVER, V6B 6P6 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 305 - 928 RICHARDS BUZZER: 675 VANCOUVER, V6B 6 BRITISH COLUMBIA	S STREET
PHONE 604.669.6996			EMAIL michael.duchnych@s	haw.ca

REASON FOR TODAY'S CALL:

There was water found pooling under my sink which led to water seeping into the apt below me. I can't find the leak and the people below me came to my apt last night indicating that a water patch was forming on their ceiling. I had just completed a rinse cycle on my dishwasher. However this seems to have been a chronic situation based on the state of my particle board cupboard condition.

DESCRIPTION OF WORK PERFORMED:

The garburator was leaking right through the bottom of the unit. I replaced the garburator with a new Badger5 and tested by filling and draining the sink multiple times while running the garburator.

QTY.	CODE	DESCRIPTION	UNIT PRICE PRICE
1	10	Supply & Install 1/2HP Badger5 Garburator	\$319.00 \$319
0		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL: \$319
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAY	
		com/feedback [1] WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL: \$334
		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARG MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE SETTLED PLETED DETERMINATION OF LEAD PIPES EXTURES CLEAN OUTS AND ANY OF	FOR BROKEN, THER DAMAGES

CUSTOMER SIGNATURE

CHARGES. E. & O. E.

2017-11-15

DATE