



DATE 2017-11-17	TECHNICIAN Darren Mann	JOB/ORDER # 7918	REFERENCE TEXT Client reference
FIRST NAME Eriko		LAST NAME Sudo	
BILLING ADDRESS COMPANY / BILLING NAME 1505 - 939 HOMER ST VANCOUVER, V6B2W6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 1505 - 939 HOMER ST, BUZZER 0309 VANCOUVER, V6B2W6 BRITISH COLUMBIA, CANADA	
PHONE 778.558.3291		EMAIL ellieca0805@gmail.com	

REASON FOR TODAY'S CALL:
 Shower valve trim and handle have become detached.

DESCRIPTION OF WORK PERFORMED:
 -When I arrived onsite I noticed a small leak coming from the stem of the cartridge within the shower valve. I replaced the cartridge(Tempress ii) within the valve and tested. -I was able to reattach the trim and handle but one of the screws used to secure the trim plate was missing. I used a small amount of silicone to help mitigate the chances of the trim plate falling off again.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Shower Cartridge - Temp II	\$209.00	\$209.00
			SUBTOTAL:	\$209.00
			GST (5%):	\$10.45
			TOTAL:	\$219.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.



_____ 2017-11-17

 CUSTOMER SIGNATURE DATE