



HST #837181627

DATE 2017-11-21	TECHNICIAN Darren Mann		JOB/ORDER # 7913	REFERENCE TEXT Client reference	
FIRST NAME Jean		LAST NAME Mistrot			
BILLING ADDRESS COMPANY / BILLING NAME 405 - 1525 PENDRELL ST. VANCOUVER, V6G 1S6 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS  405 - 1525 PENDRELL ST, BUZ#42 RICHARD(TENANT): 604.362.5020 VANCOUVER, V6G 1S6 BRITISH COLUMBIA, CANADA			
PHONE 604.569.4000		EMAIL sumistrot@gmail.com	EMAIL sumistrot@gmail.com		

## REASON FOR TODAY'S CALL:

Leaky faucet in bathtub. It's is a split diverter separate hot/cold which seems to have a removeable cartridge for each. The one side seems to have a bad gasket never allowing the faucet to be completely turned off. The main shutoff for the faucet is in the garage and shuts off the whole riser.

## DESCRIPTION OF WORK PERFORMED:

I replaced the Hot & Cold cartridges & seats in the shower valve. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Hot & Cold Shower Cartridges - Waltec	\$169.00	\$169.00
<i>Q.a</i>	(1	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$169.00
Gwe us Feedback  Please visit our feedback page at:  www.yaletownplumbing.com/feedback  Fill in the required details from your invoice and tell us how we did.  Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$8.45
			TOTAL:	\$177.45
		MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN.  SETTLED BLISTED RETERIORATION OF LEAD RIDES SUTTLIBES OF EARL OUTS AND ANY OTHER DAMAGE.		

CUSTOMER SIGNATURE

DATE