



HST #837181627

DATE 2018-01-24	TECHNICIAN Darren Mann		JOB/ORDER # 8127		REFERENCE TEXT Client reference
FIRST NAME Mandeep		LAST NAME Mahal	97		
BILLING ADDRESS COMPANY / BILLING NAME 805 - 1783 MANITOBA ST VANCOUVER, V5Y0K1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS  805 - 1783 MANITOBA STREET SISTER: 1.204.997.9551 BUZZER: 2916 VANCOUVER, V5Y0K1 BRITISH COLUMBIA, CANADA	
PHONE 1.204.510.9636	-			EMAIL mandeep.mahal@gmail.com	

REASON FOR TODAY'S CALL: leaky tap in condo bathtub

## DESCRIPTION OF WORK PERFORMED:

I replaced the mixing/pressure balance cartridge within the shower valve and tested.

Tropiaced the mixing procedure balance carriage within the shower valve and tested.								
QTY.	CODE	DESCRIPTION			PRICE			
1		Replace Geberit Shower VLV Cartridge			\$159.00			
Q	(1	eadlack wa	SUBTOTAL:	\$159.00				
Gwe us Feedback Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95			
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.  Thank You!		Is from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  NTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$166.95			
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.					

CUSTOMER SIGNATURE

DATE