

Phone: 604.727.4484 yaletownplumbing.com





2018-03-12

DATE

HST #837181627

DATE 2018-03-12	TECHNICIAN Darren Mann		JOB/ORDER # 8290	REFERENCE TEXT 18-0360
FIRST NAME Advent		LAST NAME Admin		
BILLING ADDRESS ADVENT REAL ESTA' #204 - 1168 HAMILTO VANCOUVER, V6B2S BRITISH COLUMBIA,	N ST 2		SERVICE ADDRESS 602 - 1616 COLUMBIA KRIS: 604.445.8716 VANCOUVER, BRITISH COLUMBIA,	
PHONE 604.736.6478			EMAIL andrea@adventvanco	uver.com

REASON FOR TODAY'S CALL:

Low pressure in lavatory faucet

DESCRIPTION OF WORK PERFORMED:

I removed the faucet spout and found that the original installer unfortunately connected the spout to the adaptor in such a way that it is now seized on. I cleared debris from the inlet as best I could and reinstalled. At first the faucet seemed to be functioning normally but during testing went back to low pressure and sporadic spray and then again back to normal. I removed the spout again and cleaned out the spout inlet as best I could, reinstalled and tested again. The faucet seems fine sometimes and other times the flow is sporadic. Unfortunately because of how the original installer connected the spout to the adaptor I cannot remove it to replace the pressure regulator inside. If the issue continues to be a problem for the tenant we may have to contact Dornbracht and order a new spout.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Discount Labour	\$99.00	\$99.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$99.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$4.95
			TOTAL:	\$103.95
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		

CUSTOMER SIGNATURE