

Phone: 604.727.4484 yaletownplumbing.com

HST #837181627

DATE 2018-03-23	TECHNICIAN Darren Mann		JOB/ORDER # 8324	REFERENCE TEXT Client reference
FIRST NAME Jonathan		LAST NAME Yu		
BILLING ADDRESS COMPANY / BILLING NAME 1802 - 980 COOPERAGE WAY VANCOUVER, V6B 0C3 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 1802 - 980 COOPERAGE WAY NO BUZ VANCOUVER, V6B 0C3 BRITISH COLUMBIA, CANADA	
PHONE 1.780.862.6288		EMAIL jonathanyu902@hotm	EMAIL jonathanyu902@hotmail.com	

REASON FOR TODAY'S CALL:

when I try to turn on the shower in my tub/shower, the water pressure only goes halfway to the showerhead. The tub faucet will run simultaneously at about halfpressure. Also, the water drains very slowly and pools for some time.

DESCRIPTION OF WORK PERFORMED:

-March23: I used the PowerSpin drain snake to clean the tub drain. -March26: I replaced the tub spout with a new Delta pull-down type diverter spout and tested.

QTY.	CODE	DESCRIPTION		PRICE
1		DISCOUNT - PowerSpin Drain Cleaning	\$119.00	\$119.00
1		Replace Standard Tub Spout Diverter		\$159.00
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$278.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$13.90
			TOTAL:	\$291.90

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

