

Phone: 604.727.4484 yaletownplumbing.com



HST #837181627

DATE 2018-04-04	TECHNICIAN Darren Mann		JOB/ORDER # 8332		REFERENCE TEXT Client reference
FIRST NAME Ali		LAST NAME Reynolds	97		
BILLING ADDRESS COMPANY / BILLING NAME 418 - 1820 WEST 3RD AVE VANCOUVER, V6J1K8 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 418 - 1820 WEST 3RD AVE NO BUZ VANCOUVER, V6J1K8 BRITISH COLUMBIA, CANADA	
PHONE 604.773.5022				EMAIL alir2626@gmail.com	

REASON FOR TODAY'S CALL:

Hey Darren, our bathtub drain is becoming corroded our tub spout is no longer diverting water to the shower head as it should be. We would also like the overflow drain cover/gasket (don't know the name of it) replaced while you are here just in case. I have added pictures of the 3 parts we need:)

DESCRIPTION OF WORK PERFORMED:

I replaced the tub drain with a lift and turn style drain and the tub spout with a Delta pull-down type diverter spout. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Tub Drain Trim - Standard	\$159.00	\$159.00
1		Replace Standard Tub Spout Diverter - ADD-ON PRICE	\$69.00	\$69.00
Give us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$228.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$11.40
			TOTAL:	\$239.40

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

> 2018-04-04 CUSTOMER SIGNATURE DATE