



HST #837181627

DATE 2018-05-15	TECHNICIAN Darren Mann		JOB/O 8477	RDER #	REFERENCE TEXT Client reference
FIRST NAME Jason		LAST NAME Wong	97		
BILLING ADDRESS COMPANY / BILLING NAME 1801 - 1483 HOMER ST VANCOUVER , V6Z3C7 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS 1801 - 1483 HOMER ST VANCOUVER , V6Z3C7 BRITISH COLUMBIA, CANADA	
PHONE 604.338.3348				EMAIL Joeshoegg1234@hotmail.com	

REASON FOR TODAY'S CALL:

Kitchen faucet extension don?t work. No water coming out. And also bath tub button broke

DESCRIPTION OF WORK PERFORMED:

-The tub spout was broken internally and could not be repaired. I replaced the tub spout with a new Delta pull-down type diverter spout and tested. -There is a issue with the kitchen faucet diverter. I will contact the manufacturer(Kraus) and ask about the availability of replacement parts.

TECHNICIAN RECOMMENDATIONS:

The guest bathroom shower head is attached to close to the wall. Is the connection between the shower arm and head leas it is possible for this water to leak in behind the tile. I suggest installing a longer shower arm.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00
<i>Q</i>		SUBTOTAL:	\$159.00	
Gwe us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did.		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$7.95
		s from your	TOTAL:	\$166.95
		INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		

Thank You!

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2018-05-15

CUSTOMER SIGNATURE

DATE