



2018-05-30

HST #837181627

DATE 2018-05-30	TECHNICIAN Darren Mann		JOB/OF 8538	RDER #	REFERENCE TEXT Client reference
FIRST NAME Karim		LAST NAME Allibhai			
BILLING ADDRESS COMPANY / BILLING NAME 4238 CARLETON AVE BURNABY, V5G3B6 BRITISH COLUMBIA, CANADA				SERVICE ADDRESS 311 - 289 EAST 6TH AVE LILY: 604.715.9948 CALEB: 778.926.4462 BURNABY, BRITISH COLUMBIA, CANADA	
PHONE 604.961.2228	-			EMAIL karim.allibhai@gmail.com	

REASON FOR TODAY'S CALL:

Tub faucet won?t fully shut off. *call Caleb for entry.

DESCRIPTION OF WORK PERFORMED:

The mixing/pressure balance cartridge within the shower valve failed, allowing water to flow through when the handle was in the fully off position. I replaced this cartridge and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//	Replace Gerber Mixing/PB Cartridge	\$139.00	\$139.00
<i>Q</i>		eedback warranty: Parts - Subject to Manufacturer's Warranty	SUBTOTAL:	\$139.00
	t our feedbac	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$6.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			TOTAL:	\$145.95
		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED PLISTED DETERIORATION OF LEAD PIPES SIXTURES OF AND OUTS AND ANY OTHER DAMAGE	s	