



DATE 2018-07-23	TECHNICIAN Darren Mann	JOB/ORDER # 8647	REFERENCE TEXT
FIRST NAME Cameron		LAST NAME Gray	
BILLING ADDRESS VR1819 503 - 1220 BARCLAY ST. VANCOUVER, V6E 1H3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 504 - 1220 BARCLAY ST. BUZZER: 34 VANCOUVER, V6E 1H3 BRITISH COLUMBIA, CANADA	
PHONE 604-738-5558		EMAIL cameron.gray@telus.net	

REASON FOR TODAY'S CALL:  
 -Toilet tank is leaking between tank and bowl when flushed. -The shower is draining very slowly.

DESCRIPTION OF WORK PERFORMED:  
 -I removed the toilet tank and reinstalled with a new tank to bowl gasket, tank bolts, and braided supply line. Tested and in no other leaks detected. -I used the PowerSpin drain snake to clean the shower drain and tested.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Tank To Bowl Gasket - Standard	\$169.00	\$169.00
1		PowerSpin - Drain Cleaning Add-On	\$50.00	\$50.00

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

**WARRANTY:** **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2018-07-23

CUSTOMER SIGNATURE

DATE

SUBTOTAL:	\$219.00
GST (5%):	\$10.95
TOTAL:	\$229.95