



2018-08-01

DATE

HST #837181627

DATE 2018-08-01	TECHNICIAN Darren Mann		JOB/O 8741	RDER #	REFERENCE TEXT
FIRST NAME Easyrent		LAST NAME Admin			
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. 100 - 1290 HOMER ST VANCOUVER, V6B2Y5 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 3009 - 833 SEYMOUR ST, BUZ CAMILA: 778.378.7983 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.662.3279				EMAIL info@easyrent.ca	

REASON FOR TODAY'S CALL:

Tub/shower diverter not working.

DESCRIPTION OF WORK PERFORMED:

I was able to repair the tub spout diverter by reattaching all of the pieces that came loose internally. Tested and in good working order

QTY.	CODE	DESCRIPTION				PRICE
1		Discount Labour	7		\$99.00	\$99.00
Q	(1	oodlack	WARRANTY:	ITY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$99.00
	we us Feedback se visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.95
www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		INTEDEST AT	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$103.95	
		MADE THAT MATERIALS I SETTLED, RU RESULTING	SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, JSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK			

CUSTOMER SIGNATURE