



HST #837181627

DATE 2018-08-16	TECHNICIAN Darren Mann		JOB/ORDER # 8790		REFERENCE TEXT 18-1105	
FIRST NAME Advent		LAST NAME Admin				
BILLING ADDRESS ADVENT REAL ESTATE SERV #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS  1104 - 1155 HOMER ST TIM: 604.616.5742 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478				EMAIL andrea@adventvancouver.com		

## REASON FOR TODAY'S CALL:

Shower - Hand Held: broken at base that connects to the main shower line, possible internal hose is cracked.

## DESCRIPTION OF WORK PERFORMED:

The shower spray hose was leaking internally and could not be repaired. I replaced this hose with new and tested.

QTY.	CODE	DESCRIPTION			PRICE
1	1	Discount Labour		\$99.00	\$99.00
1	2201364	LS60MH-CP 60 MTL HSE		\$35.00	\$35.00
Gwe us Feedback WARRANTY:		warranty:	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$134.00
	Please visit our feedback page at:		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.70
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  EREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY BE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		\$140.70

Thank You!

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOW MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND TH/MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPECTIVED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AT RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATER	NT CHARGES AND ONSIBLE FOR BROKEN, ND ANY OTHER DAMAGES
CHARGES. E. & O. E.	
	2018-08-16
CUSTOMER SIGNATURE	DATE