



DATE 2018-08-31	TECHNICIAN Darren Mann	JOB/ORDER # 8825	REFERENCE TEXT
FIRST NAME David		LAST NAME Yang	
BILLING ADDRESS RENT IT FURNISHED 110 - 1020 MAINLAND STREET VANCOUVER, V6B2T4 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 409 - 289 ALEXANDER ST ARCHIE: 604.992.3892 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 778.988.8470		EMAIL PMVan1@rentitfurnished.com	

REASON FOR TODAY'S CALL:
Tub/shower diverter not working.

DESCRIPTION OF WORK PERFORMED:
The tub spout diverter was broken internally. The original installer soldered the spout adaptor to the 1/2" copper coming out of the wall so I installed a matching Delta spout that fits with the unremovable adaptor. Tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter	\$159.00	\$159.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$159.00
GST (5%):	\$7.95
TOTAL:	\$166.95

_____ 2018-08-31
 CUSTOMER SIGNATURE DATE