



DATE 2018-09-21	TECHNICIAN Darren Mann	JOB/ORDER # 8874	REFERENCE TEXT Client reference
FIRST NAME Matthew		LAST NAME Rubin	
BILLING ADDRESS COMPANY / BILLING NAME 2901 - 1495 RICHARDS ST VANCOUVER, V6Z3E3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2901 - 1495 RICHARDS ST, BUZZER 1193 VANCOUVER, V6Z3E3 BRITISH COLUMBIA, CANADA	
PHONE 604.700.5223		EMAIL fly727matt@msn.com	

REASON FOR TODAY'S CALL:
 In my washroom, the bathtub faucet is continually leaking and needs repair or replacement.


DESCRIPTION OF WORK PERFORMED:
 -The Mixing Cartridge within the Shower valve was broken. I replaced the mixing and pressure balance cartridges, tested and in good working order.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Mixing & Pressure Balance Cartridge - HC180	\$229.00	\$229.00
SUBTOTAL:				\$229.00
GST (5%):				\$11.45
TOTAL:				\$240.45

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY
LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.


 _____ 2018-09-21
 CUSTOMER SIGNATURE DATE