

Phone: 604.727.4484 yaletownplumbing.com

2018-10-11

HST #837181627

DATE 2018-10-11	TECHNICIAN Darren Mann		JOB/ORDER # 8925	REFERENCE TEXT Client reference
FIRST NAME Tara		LAST NAME Gardner		
BILLING ADDRESS COMPANY / BILLING NAME 1806 - 1255 SEYMOUR ST VANCOUVER, V6B0H1 BRITISH COLUMBIA, CANADA			SERVICE ADDRES 1806 - 1255 SEYMO VANCOUVER, V6B BRITISH COLUMBI	OUR ST, BUZZER 872 0H1
PHONE 778.386.4964			EMAIL taravancity@gmail.c	com

REASON FOR TODAY'S CALL:

My tenant has informed me that the shower diverter is not shifting the water from the spout to the shower head (started last week and is now getting worse). She also says the garburator continuously stops working and flips the reset button. The garburator is fairly new, so there may just be something blocking it or it may be an electrical issue.

DESCRIPTION OF WORK PERFORMED:

-I replaced the tub spout with a new Delta pulldown type diverter spout and tested. -I was able to unjam the garburator and tested by filling and draining the sink

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//.	Replace Standard Tub Spout Diverter	\$159.00	\$159.00
<i>Q.</i>	(1	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$159.00
	Gwe us Feedback lease visit our feedback page at:	LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.95
Fill in the required details from your invoice and tell us how we did. Thank Youl			TOTAL:	\$166.95
		MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		