

(E) @SimplyPlumbing f YaletownPlumbing

## HST #837181627

DATE 2018-10-15	TECHNICIAN Darren Mann		JOB/O 8928	RDER #	REFERENCE TEXT Client reference
FIRST NAME Colin		LAST NAME Doig	7		
BILLING ADDRESS RE/MAX CREST REALTY WESTSIDE 1428 WEST 7TH AVE VANCOUVER, V6H1C1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 3807 - 1408 STRATHMORE MEWS BUZ#1266 SURIANA: 778.378.9937 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.417.9003				EMAIL colin@colindoig.com	

REASON FOR TODAY'S CALL:

Guest bathroom tub faucet won?t shut off.

## DESCRIPTION OF WORK PERFORMED:

The cartridge within the shower valve failed and would not shut off the flow of water. I replaced this cartridge and tested.-While onsite the tenant mentioned the tub spout in the master bathroom was not fully diverting water to the shower. I replaced this tub spout with a new Delta pulldown type diverter spout and tested.

<b>QTY.</b>	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Shower Cartridge - Temp II	\$209.00	\$209.00
1		Replace Standard Tub Spout Diverter - Discounted	\$69.00	\$69.00
0	Concert Concerts warranty: Parts - SUBJECT TO MANUFACTURER'S WARRANTY			
Give us Feedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$13.90
		com/feedback [1] WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$291.90
		VE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETU ED RUSTED DETERIORATION OR LEAD PIPES EXTURES CLEAN OUTS AND ANY OTHER DAMAGES.		

2018-10-15

CUSTOMER SIGNATURE

DATE