



2018-12-03

DATE

HST #837181627

DATE 2018-12-03	TECHNICIAN Darren Mann		JOB/O 9027	RDER #	REFERENCE TEXT Client reference
FIRST NAME Pat		LAST NAME Dairon	97		
BILLING ADDRESS COMPANY / BILLING NAME 706 - 1500 HORNBY ST VANCOUVER, V6Z2R1 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 706 - 1500 HORNBY ST, BUZZ VANCOUVER, V6Z2R1 BRITISH COLUMBIA, CANADA	
PHONE 604.647.0442			EMAIL patsydairon@gmail.com		

REASON FOR TODAY'S CALL:

-Water level in Kohler toilet(bowl) low after flushing. -Shower valve(Kohler) handle loose and pointing in the wrong direction.

DESCRIPTION OF WORK PERFORMED:

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$109.00	\$109.00
2		SUBTOTAL:	\$109.00	
Gwe us Jeedback Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$5.45
			TOTAL:	\$114.4
		WE did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED PLISTED DETERIORATION OF LEAD PIPES FIXTURES CLEAN OUTS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE