

HST #837181627

DATE 2019-01-29	TECHNICIAN Darren Mann			REFERENCE TEXT 19-0169	
FIRST NAME Advent		LAST NAME Admin			
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 902 - 1308 HORNBY ST TUANRUI: 778.991.3477 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478			EMAIL andrea@adventvanco	EMAIL andrea@adventvancouver.com	

REASON FOR TODAY'S CALL:

Tub faucet loose, not working well for tub but shower working fine.

DESCRIPTION OF WORK PERFORMED:

-There was a set screw inside the tub spout assembly that came loose, causing the spout to fly off while they were filling the tub. I tightened this set screw and reinstalled the spout. Tested and in good working order.

QTY.	CODE	DESCRIPTION			PRICE
1		Discount Labour		\$99.00	\$99.00
ee	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$99.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your invoice and tell us how we did. Thank Youl			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$4.95
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$103.95
		we did.	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE