



HST #837181627

UNIT PRICE

PRICE

TECHNICIAN Darren Mann		JOB/ORDER # 9172	REFERENCE TEXT Client reference	
	LAST NAME Rowe			
	19	1005 - 928 RICHARI VANCOUVER, V6B6	DS ST, BUZZER 694 6P6	
		EMAIL terryrowe2018@iclor	ud.com	
		Darren Mann  LAST NAME	Darren Mann  LAST NAME Rowe  SERVICE ADDRESS  1005 - 928 RICHAR VANCOUVER, V6B6 BRITISH COLUMBIA  EMAIL	Darren Mann  9172  Client reference  LAST NAME Rowe  SERVICE ADDRESS  1005 - 928 RICHARDS ST, BUZZER 694 VANCOUVER, V6B6P6 BRITISH COLUMBIA, CANADA

## REASON FOR TODAY'S CALL:

Master Bathroom: The faucet for the bathtub has a slow drip.

## **DESCRIPTION OF WORK PERFORMED:**

CODE

The cartridge within the shower valve failed, creating a slow steady drip. I replaced this cartridge and tested.

1 Replace Single Cartridge - Moen			\$129.00	\$129.00	
1	2398043	GP84995 FLAPPER ASS	FLAPPER ASSM KIT		
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$149.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$155.45
		s from your	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		

**DESCRIPTION** 

invoice and tell us how we did. MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT, YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN. SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES <u> Thank You!</u> RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

1. 8.70

CUSTOMER SIGNATURE

2019-02-12