

HST #837181627

DATE 2019-02-28	TECHNICIAN Darren Mann		JOB/O 9198	RDER#	REFERENCE TEXT Client reference	
FIRST NAME Bert		LAST NAME Peers	707			
BILLING ADDRESS COMPANY / BILLING NAME 203 - 989 BEATTY ST VANCOUVER, V6Z3C2 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 203 - 989 BEATTY ST, BUZZE VANCOUVER, V6Z3C2 BRITISH COLUMBIA, CANADA		
PHONE 604.446.5021				EMAIL peirz@hotmail.com		

REASON FOR TODAY'S CALL: Replace kitchen faucet.

DESCRIPTION OF WORK PERFORMED: I installed the new kitchen faucet and tested.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1		Supply & Install New Moen Banbury Faucet			\$309.00
		war	RRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$309.00
			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$15.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	TOTAL:	\$324.45
		IN	STEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY HADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND		

Thank You!

CUSTOMER SIGNATURE	2019-02-28 ———————————————————————————————————
MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATI CHARGES. E. & O. E.	AND ANY OTHER DAMAGES
MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND TI MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RES SETTI ED BUSTED DETERINDATION OF LEAD BIESS SUTURES OF AN OUTS	SPONSIBLE FOR BROKEN,