



DATE 2019-04-16	TECHNICIAN Darren Mann	JOB/ORDER # 9321	REFERENCE TEXT Client reference
FIRST NAME Patrick		LAST NAME Wong Fung	
BILLING ADDRESS COMPANY / BILLING NAME 1331 HOMER STREET VANCOUVER, V6B 5M5 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #804 - 1331 HOMER STREET, BUZZER 5075 VANCOUVER, V6B 5M5 BRITISH COLUMBIA, CANADA	
PHONE 604-688-5433		EMAIL pwongfung@shaw.ca	

REASON FOR TODAY'S CALL:

1. Kitchen tap (Moen) leaking; where the hose attaches to the tap is leaking as well. 2. Bath drain chrome ring is cracked.

DESCRIPTION OF WORK PERFORMED:

-I installed a new Moen deck faucet and tested. I replaced the tub drain trim with a new lift & turn style drain.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Replace Tub Drain Trim - Standard	\$159.00	\$159.00
1		Moen Banbury Deck Faucet - Installed	\$259.00	\$259.00
SUBTOTAL:				\$418.00
GST (5%):				\$20.90
TOTAL:				\$438.90

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.
TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

 CUSTOMER SIGNATURE

2019-04-16

 DATE