

(B) @SimplyPlumbing | YaletownPlumbing



HST #837181627

DATE 2019-04-17	TECHNICIAN Darren Mann		JOB/ORDER # 9326		REFERENCE TEXT Client reference
FIRST NAME Jerome		LAST NAME Deis			
BILLING ADDRESS COMPANY / BILLING NAME 2888 WEST 19TH AVE VANCOUVER, V76L1E5 BRITISH COLUMBIA, CANADA				#1706 - 1255 SEYMOUR ST BU OLIVIA(TENANT): 604.812.932. VANCOUVER, BRITISH COLUMBIA, CANADA	4
PHONE 604.230.5151				EMAIL jeromedeis@remax.net	

REASON FOR TODAY'S CALL:

Tub spout diverter not working.

DESCRIPTION OF WORK PERFORMED:

-The tub spout was broken internally and could not be repaired. I replaced the tub spout with new and tested. -The tenant mentioned while onsite that the toilet tank lever was broken. I replaced this tank lever as well.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1		Replace Standard Tub Spout Diverter		\$159.00	\$159.00
1	11	Toilet Tank Lever		\$10.00	\$10.00
<i>Q.</i>	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$169.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$8.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		\$177.45

Thank You!

invoice and tell us how we did.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKN MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT R SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUT RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MA	THAT CHARGES AND ESPONSIBLE FOR BROKEN, S AND ANY OTHER DAMAGES
CHARGES. E. & O. E.	
	2019-04-17
CUSTOMER SIGNATURE	DATE