

HST #837181627

DATE 2019-08-06	TECHNICIAN Darren Mann		JOB/ORDER # 9570		REFERENCE TEXT 19-1099	
FIRST NAME Advent		LAST NAME Admin				
BILLING ADDRESS ADVENT REAL ESTATE SERVICES LTD. #204 - 1168 HAMILTON ST VANCOUVER, V6B2S2 BRITISH COLUMBIA, CANADA			1904 - 6 HEALI: VANCO	SERVICE ADDRESS  1904 - 667 HOWE ST HEALI: 778.689.7176 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604.736.6478			EMAIL andrea@adventvancouver.com			

## REASON FOR TODAY'S CALL:

Shower Head not getting a lot of water pressure because the spray hose attached to it is leaking.

## DESCRIPTION OF WORK PERFORMED:

I replaced the broken shower spray hose and tested. Pressure is back to normal.

QTY.	CODE	DESCRIPTION			PRICE
1	//	Discount Labour		\$99.00	\$99.00
1	1/2	60? Shower Spray Hose		\$35.00	\$35.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1] Fill in the required details from your  Parts - SUBJECT TO MANUFACTURER'S WARRANTY  LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.		SUBTOTAL:	\$134.00		
			MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	GST (5%):	\$6.70
		s from your		TOTAL:	\$140.70

Thank You!

invoice and tell us how we did.

N N S	INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DU MADE THAT SERVICES LISTED ABOVE ARE SATISFACTOR MATERIALS LISTED HEREON ARE CORRECT. YALETOWN SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIX RESULTING FROM CLEANING OR REPAIRING EXISTING FI TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN AI	Y COMPLETED AND THAT PLUMBING IS NOT RESPOI TURES, CLEAN OUTS AND XTURES OR PIPING.	CHARGES AND NSIBLE FOR BROKEN, ANY OTHER DAMAGES
_	CHARGES, E. & O. E.		
`			
			2019-08-06
	CUSTOMER SIGNATURE		DATE