

Phone: 604.727.4484 yaletownplumbing.com



HST #837181627

DATE 2019-09-05	TECHNICIAN Darren Mann		JOB/ORDER # 9623	REFERENCE TEXT Client reference
FIRST NAME Nicole		LAST NAME Salvian		
BILLING ADDRESS COMPANY / BILLING NAME 1807 - 583 BEACH CR VANCOUVER, V6Z3E6 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS  1807 - 583 BEACH CR, BUZZER 1120 IRENE(MOM: 604-240-4130 VANCOUVER, V6Z3E6 BRITISH COLUMBIA, CANADA	
PHONE 604.217.7604			EMAIL nicolesalvian@hotma	il.com

## REASON FOR TODAY'S CALL:

Stopper that changes the water flow from Bath to shower popped out and no longer works. Want to also put in a new shower head.

## DESCRIPTION OF WORK PERFORMED:

-I replaced the diverter mechanism within the tub spout diverter and tested. -I installed the customer supplied shower spray hose and head and tested.

## TECHNICIAN RECOMMENDATIONS:

The shower spray head holder is cracked and barely holds the spray head. This shower bar and holder should be replaced.

QTY.	CODE	DESCRIPTION		PRICE
1	//	Repair Latore Tub Spout Diverter		\$139.00
Canal warranty: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY			SUBTOTAL:	\$139.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF	GST (5%):	\$6.95
			TOTAL:	\$145.95

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2019-09-05

CUSTOMER SIGNATURE

DATE