



HST #837181627

_		
	@SimplyPlumbing	
	@SimplyPillimping	
	grantipiti imittottig	
	_ , ,	

YaletownPlumbing

DATE 2012-06-25	TECHNICIAN Evan Brandle		JOB/O 530	RDER #	REFERENCE TEXT
FIRST NAME Fred		LAST NAME Vertone			
BILLING ADDRESS		//0	//,	SERVICE ADDRESS	
WEST VANCOUVER, BRITISH COLUMBIA, CANAD	Α			#404 - 1433 HARWOOD ST VANCOUVER, BRITISH COLUMBIA, CANAD	A
PHONE 604.926.3806				EMAIL fred.vertone@shaw.ca	
REASON FOR TODAY'S CAL	L:				

-leak in ceiling of unit 404

DESCRIPTION OF WORK PERFORMED:

-cut hole in ceiling of unit #404 to find problem to be the toilet in unit #504. Lifted toilet in #504 found the flange was rotted so I cut out and replaced with a twist and set flange. Julia wanted to keep the old toilet that was there so I replaced all guts in toilet to make it new again then re set it. -snaked tub in #404 -snaked tub in #402 snaked tub in #504

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
7		Discount Labour 75		\$75.00	\$525.00
1		All Materials Used		\$60.00	\$60.00
Please visit our feedback page at: LABOL MAINT		WARRANTY	PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.	SUBTOTAL:	\$585.00
				HST (12%):	\$70.20
				TOTAL:	\$655.20

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES I MATERIALS LISTED HER SETTLED, RUSTED, DET	IL RATE IS CHARGED ON PAST DI LISTED ABOVE ARE SATISFACTO REON ARE CORRECT. YALETOWN 'ERIORATION, OR LEAD PIPES, FI NNING OR REPAIRING EXISTING F	RY COMPLETED AND THA PLUMBING IS NOT RESPO XTURES, CLEAN OUTS AN	T CHARGES AND ONSIBLE FOR BROKEN,
	AMOUNTS CONTAINED HEREIN A		IALS AND TRUCK
CHARGES, E. & O. E.		,	
			2012-06-25
	CUSTOMER SIGNATURE		DATE