



DATE 2012-11-28	TECHNICIAN Darren Mann	JOB/ORDER # 943	REFERENCE TEXT Client reference
FIRST NAME Romy		LAST NAME Buxton	
BILLING ADDRESS COMPANY / BILLING NAME 2496 WEST 5TH AVE VANCOUVER, V6K1S8 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS 2496 WEST 5TH AVE VANCOUVER, V6K1S8 BRITISH COLUMBIA, CANADA	
PHONE 604.313.6607		EMAIL romybuxton@yahoo.ca	

REASON FOR TODAY'S CALL:
-leak in ceiling below tub.

DESCRIPTION OF WORK PERFORMED:
-removed shower trim to find slow drip from the shower valve leaking behind the tile. -replaced tub drain trim and noticed the overflow is installed too high causing the gasket to sit high and not make a tight seal.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Labour	\$99.00	\$99.00
1	2072330	129-501RP TUB TRIM KIT CP	\$35.00	\$35.00
SUBTOTAL:			\$134.00	\$134.00
HST BC (12%):			\$16.08	\$16.08
TOTAL:			\$150.08	\$150.08

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

Romy Buxton

2012-11-28

CUSTOMER SIGNATURE

DATE