




HST #837181627

	,	
B	@Simp	lyPlumbing



DATE 2012-12-10	TECHNICIAN Kristian Evans		JOB/ORDER # 980	REFERENCE TEXT Client reference	
FIRST NAME Patrick		LAST NAME Johnson			
BILLING ADDRESS L' HERMITAGE HOTI #662 - 788 RICHARD VANCOUVER, BRITISH COLUMBIA	SST	19	SERVICE ADDRESS #662 - 788 RICHARD VANCOUVER, BRITISH COLUMBIA	os st	
PHONE 778.235.5590			EMAIL pjohnson@lhermitage	evancouver.com	

REASON FOR TODAY'S CALL:

-replace undermount lav sink. (Sink ready for pick up at Emco under "Patrick")

DESCRIPTION OF WORK PERFORMED:

-remove and replace lav undermount sink.

QTY.	CODE	DESCRIPTION		UNIT PRICE	PRICE
1	y	Replacement of K2215 Ur	ndermount Lav Sink	\$539.00	\$539.00
0	Gwe us Feedback Please visit our feedback page at:		PARTS - SUBJECT TO MANUFACTURER'S WARRANTY LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	SUBTOTAL:	\$539.00
_				HST (12%):	\$64.68
invoice and tell us how we did.		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. EST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$603.68
		we did. MADE	THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND PIALS LISTED RESEAU ARE CORSECT VALETOWN BLIMBING IS NOT SECONDISISED FOR PROKEN		

Thank You!

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AI RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.	ND ANY OTHER DAMAGES
EERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATER CHARGES. E. & O. E.	RIALS AND TRUCK
	2012-12-10
CUSTOMER SIGNATURE	DATE