



DATE 2013-02-08	TECHNICIAN darren mann	JOB/ORDER # 1237	REFERENCE TEXT Client reference
FIRST NAME Satnam		LAST NAME Bhangu	
BILLING ADDRESS EASYRENT REAL ESTATE SERVICES LTD. #501 - 1111 W HASTINGS ST VANCOUVER, V6E-2J3 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #2703 - 1255 SEYMOUR ST BUZ#974 VANCOUVER, BRITISH COLUMBIA, CANADA	
PHONE 604.662.3279		EMAIL admin@easyrent.ca	

REASON FOR TODAY'S CALL:
 -tub/shower diverter not working.

DESCRIPTION OF WORK PERFORMED:
 -the tub/shower diverter had come apart, i removed the diverter assembly, re-assembled it and installed. Seemed to work fine but came apart again. -replaced tub spout diverter.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1.5		Discount Labour 89	\$89.00	\$133.50
1	2180009	ESP2 EMCO DIV SPT CP	\$21.00	\$21.00

Give us Feedback
 Please visit our feedback page at:
www.yaletownplumbing.com/feedback [1]
 Fill in the required details from your invoice and tell us how we did.
Thank You!

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

SUBTOTAL:	\$154.50
HST (12%):	\$18.54
TOTAL:	\$173.04

_____ 2013-02-08 _____
 CUSTOMER SIGNATURE DATE