



DATE 2013-09-11	TECHNICIAN Kristian Evans	JOB/ORDER # 2161	REFERENCE TEXT
FIRST NAME Maxwell	LAST NAME Meyer		
BILLING ADDRESS #2401 - 1295 RICHARDS BUZ#207 VANCOUVER, V6B 1B7 BRITISH COLUMBIA, CANADA		SERVICE ADDRESS #2401 - 1295 RICHARDS BUZ#207 VANCOUVER, V6B 1B7 BRITISH COLUMBIA, CANADA	
PHONE 604.329.9698		EMAIL docmax19@hotmail.com	

REASON FOR TODAY'S CALL:

-slow drain bathroom sink. -spraying from tub faucet when shower lever activated

DESCRIPTION OF WORK PERFORMED:

-Snaked and cleaned out ensuit lav drain. -replaced tub spout.

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1		Clear drain using PowerSpin / Lavatory	\$139.00	\$139.00
1		Replace Standard Tub Spout Diverter - ADD-ON PRICE	\$89.00	\$89.00

SUBTOTAL:	\$228.00
GST (5%):	\$11.40
TOTAL:	\$239.40

**Give us Feedback**  
 Please visit our feedback page at:  
[www.yaletownplumbing.com/feedback](http://www.yaletownplumbing.com/feedback) [1]  
 Fill in the required details from your invoice and tell us how we did.  
**Thank You!**

WARRANTY: **PARTS** - SUBJECT TO MANUFACTURER'S WARRANTY

**LABOUR** - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.

INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.  
**TERMS:** NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.

2013-09-11

CUSTOMER SIGNATURE

DATE