





HST #837181627

DATE 2014-03-18	TECHNICIAN Darren Mann		JOB/ORDER # 3125	REFERENCE TEXT Client reference	
FIRST NAME Jeff		LAST NAME Chu			
BILLING ADDRESS COMPANY / BILLING NAME 1318 HOMER STREET VANCOUVER, V6B6A7 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS #1202 - 1318 HOMER STREET BUZ#690 VANCOUVER, V6B6A7 BRITISH COLUMBIA, CANADA		
PHONE 604.351.0828			EMAIL 388drake@gmail.com	EMAIL 388drake@gmail.com	

REASON FOR TODAY'S CALL:

-replace tub spout with diverter.

DESCRIPTION OF WORK PERFORMED:

-replaced tub spout with diverter.

TECHNICIAN RECOMMENDATIONS:

-informed home owner that they should never push down on the diverter when shower is pressurized. -the cracking in the tile should be repaired as there is a possibility a leak will eventually develope.

QTY.	CODE	DESCRIPTION			PRICE
1		Replace Standard Tub Spout Diverter		\$139.00	\$139.00
WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$139.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	GST (5%):	\$6.95
		s from your		TOTAL:	\$145.95

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK

CHARGES. E. & O. E.

2014-03-18

CUSTOMER SIGNATURE

DATE