

YALETOWN PLUMBING SERVICES LTD
1503-1255 Seymour St. Vancouver, BC V6B 0H1 Phone: 604.727.4484 yaletownplumbing.com





HST #837181627

DATE 2014-09-19	TECHNICIAN Darren Mann		JOB/ORDER # 3826		REFERENCE TEXT Client reference
FIRST NAME Evan		LAST NAME Wang	707		
BILLING ADDRESS COMPANY / BILLING NAME 5605 HAMPTON PLACE VANCOUVER, V6T 2H2 BRITISH COLUMBIA, CANADA	A			SERVICE ADDRESS 210 - 5605 HAMPTON PLACE BUZZER: 1022 VANCOUVER, V6T 2H2 BRITISH COLUMBIA, CANADA	.
PHONE 604-773-6561				EMAIL wang.evan@yahoo.ca	

REASON FOR TODAY'S CALL:

"Moen single lever bathtub facuet broke off when attempting to turn on the water. The central metal stem that should be connected to the cartridge broke off at the base of the wall."

DESCRIPTION OF WORK PERFORMED:

Replaced cartridge in Moen shower valve.

QTY.	CODE	DESCRIPTION			PRICE
1		Replace Single Cartri	\$129.00	\$129.00	
0	WARRANTY		ARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$129.00
Gwe us Feedback Please visit our feedback page at:			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$6.45
	www.yaletownplumbing.com/feedback [1] Fill in the required details from your		WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$135.45
invoice and tell us how we did.		ve did.	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,		

Thank You!

SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E. CUSTOMER SIGNATURE DATE