





HST #837181627

DATE 2014-11-07	TECHNICIAN Darren Mann		JOB/ORDER # 4059		REFERENCE TEXT Client reference
FIRST NAME Andrew		LAST NAME Sandford			
BILLING ADDRESS COMPANY / BILLING NAME 1009 EXPO BOULEVARD VANCOUVER, V6Z2V9 BRITISH COLUMBIA, CANADA		9	4	SERVICE ADDRESS 905 - 1009 EXPO BOULEVARD BUZZER: 1659 VANCOUVER, V6Z2V9 BRITISH COLUMBIA, CANADA	
PHONE 604-868-4393				EMAIL asandford@live.ca	

REASON FOR TODAY'S CALL:

"Two bath tub drains need cleaning out. One has two plastic penguins stuck in it! I would also like a pop up stopper installed in each bath."

DESCRIPTION OF WORK PERFORMED:

Installed new tub drain trims on both tubs and used the PowerSpin drain snake to clean the drains in each tub.

QTY.	CODE		UNIT PRICE	PRICE	
1		Install 2 Tub Drain Trim Kits	\$199.00	\$199.00	
2	1	PowerSpin - Drain Cleaning Ad	\$50.00	\$100.00	
Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				SUBTOTAL:	\$299.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			<u>LABOUR</u> - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$14.95
		s from your	WARRANTY ON CUSTOMER SUPPLIED MATERIALS. FREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY		\$313.95

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING.

 $\underline{\textbf{TERMS}}\text{: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK}$ CHARGES. E. & O. E.

2014-11-07 CUSTOMER SIGNATURE