

YALETOWN PLUMBING SERVICES LTD
1503-1255 Seymour St. Vancouver, BC V6B 0H1 Phone: 604.727.4484 yaletownplumbing.com



2014-12-12

DATE



HST #837181627

DATE 2014-12-12	TECHNICIAN Darren Mann		JOB/O 4165	RDER #	REFERENCE TEXT Client reference
FIRST NAME Anna		LAST NAME Filippova			
BILLING ADDRESS - 977 MAINLAND ST VANCOUVER, V6B1T2 BRITISH COLUMBIA, CANADA		19	4	SERVICE ADDRESS  2208 - 977 MAINLAND ST VANCOUVER, V6B1T2 BRITISH COLUMBIA, CANADA	
PHONE 604-244-2214				EMAIL anna88497@gmail.com	

## REASON FOR TODAY'S CALL:

## DESCRIPTION OF WORK PERFORMED:

-The faucet handle set screw was loose, when I removed the trim I also noticed the cartridge was allowing water to seep out through the stem. I replaced the

QTY.	CODE	DESCRIPTION	UNIT PRICE	PRICE
1	//	Replace Mixing & Pressure Balance Cartridge - PBR40	\$189.00	\$189.00
<i>Q</i>		WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$189.00
Gwe us Feedback  Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your invoice and tell us how we did.  Thank You!		LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF  MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$9.45
			TOTAL:	\$198.45
		WE did.  MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND  MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN,  SETTLED RUSTED DETERIORATION OR LEAD PIPES STYLIPES CLEAN QUITS AND ANY OTHER DAMAGES.		

CUSTOMER SIGNATURE

<sup>&</sup>quot;I have la Torre bathtub faucet, its handle has fallen off"