



HST #837181627

DATE 2015-09-16	TECHNICIAN Darren Mann		JOB/ORDER # 5272		REFERENCE TEXT Client reference	
FIRST NAME Corrine		LAST NAME Nishi				
BILLING ADDRESS N/A 2577 WILLOW STREET VANCOUVER, V5Z 3N8 BRITISH COLUMBIA, CANADA			4	SERVICE ADDRESS 405 - 738 EAST 29TH AVE BUZ#178 604.565.6468 VANCOUVER, BRITISH COLUMBIA, CANADA		
PHONE 604-879-4823	_			EMAIL cknishi@shaw.ca		

REASON FOR TODAY'S CALL:

-toilet periodically making trickling noise(toilet was recently repaired by us) -tub/shower diverter not fully functional.

DESCRIPTION OF WORK PERFORMED:

-i tested the tollet and everything seems to be liustling as normal with no signs of water furningi replaced the tub spout with a new pull-down type belta spout.									
QTY. CODE	DESCRIPTION	UNIT PRICE	PRICE						
1 Re	eplace Standard Tub Spout Diverter	\$149.00	\$149.00						
Gwe us Fee	WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$149.00						
Please visit our feedback page	ge at: LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45						
www.yaletownplumbing.com Fill in the required details fro		TOTAL:	\$156.45						
Thank You!	MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.								

CUSTOMER SIGNATURE

DATE