

(B) @SimplyPlumbing | YaletownPlumbing

HST #837181627

DATE 2015-10-05	TECHNICIAN Darren Mann		JOB/ORDER # 5355	REFERENCE TEXT Client reference
FIRST NAME Allan		LAST NAME Toellner		
BILLING ADDRESS COMPANY / BILLING NAME 161 W GEORGIA ST APT# 318 VANCOUVER, V6B0K9 BRITISH COLUMBIA, CANADA			SERVICE ADDRESS 318 - 161 W GEORGIA ST APT# 318 BUZZER: 5028 VANCOUVER, V6B0K9 BRITISH COLUMBIA, CANADA	
PHONE 6049998131			EMAIL allan.toellner@gmail.c	com

REASON FOR TODAY'S CALL:

Our shower diverter (plunger that switches water flow from shower head to tub faucet) will not divert water to the shower head. Even when it's being forcibly held up, it mostly flows through the tub faucet. The faucet assembly does not have an allen setscrew (faucet threaded onto the water pipe?).

DESCRIPTION OF WORK PERFORMED:

I replaced the tub spout with a new Delta Pulldown type and tested.

QTY.	CODE	DESCRIPTION			PRICE
1		Replace Standard Tub Spout Diverter			\$149.00
0	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY				\$149.00
Please visit our feedback page at: www.yaletownplumbing.com/feedback [1] Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO	GST (5%):	\$7.45
			WARRANTY ON CUSTOMER SUPPLIED MATERIALS. INTEREST AT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS. ACKNOWLEDGEMENT IS HEREBY	TOTAL:	\$156.45
Thank You!			MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E.		

CUSTOMER SIGNATURE

DATE