

Phone: 604.727.4484 yaletownplumbing.com

(B) @SimplyPlumbing | | YaletownPlumbing



HST #837181627

DATE 2015-10-09	TECHNICIAN Darren Mann		JOB/ORDER # 5373	REFERENCE TEXT Client reference	
FIRST NAME Dawn-Rae		LAST NAME McLaren			
BILLING ADDRESS COMPANY / BILLING NAME 2175 SALAL DRIVE (ARBUTUS WALK) VANCOUVER, V6K 4V2 BRITISH COLUMBIA, CANADA			#202 - 2175 SALAL VANCOUVER, V6K	SERVICE ADDRESS  #202 - 2175 SALAL DRIVE (ARBUTUS WALK), BUZZER 650 VANCOUVER, V6K 4V2 BRITISH COLUMBIA, CANADA	
PHONE 604-733-9633			EMAIL mclaren5@telus.ne	EMAIL mclaren5@telus.net	

## REASON FOR TODAY'S CALL:

Kitchen faucet loose Shower handle loose Lavatory faucet sprays to right Kitchen sink drains slow \*\*-if we can simply re-tighten the kitchen faucet to the sink this can be done free of charge while onsite. -unfortunately we cannot shorten the spray hose. -we can replace the tub drain with a new lift & turn style drain for \$159+GST -if the shower valve handle can be re-secured by making and adjustment this will be done free of charge while onsite. -we don?t do re-caulking but these guys do:) -we can try replacing the aerator of the lavatory faucet that sprays to the right. \$10+GST -each drain that requires the use of our PowerSpin drain snake while on site will be \$50+GST -unfortunately we do not provide gas services any longer.

## DESCRIPTION OF WORK PERFORMED:

-I replaced the tub drain with a new lift & turn style drain. -I replaced the lavatory faucet aerator. -The screw in the handle just barely meets the cartridge it attaches to and the threads are stripped. A new, longer screw will have to be found and installed. -I re-secured the kitchen faucet to the countertop. This type of faucet(Moen) has only one threaded nut to secure it to the countertop. This nut loosens up over time and will likely loosen up again in the future. -I used the PowerSpin drain snake to clean the kitchen sink drain. Tested by filling and draining the sink.

QTY.	CODE		DESCRIPTION	UNIT PRICE	PRICE
1		Replace Tub Drain Trim - Standard		\$159.00	\$159.00
1		15/16 M Aerator		\$10.00	\$10.00
1		PowerSpin - ADD-ON PRICING		\$50.00	\$50.00
<i>Q.</i>	Gwe us Feedback WARRANTY: PARTS - SUBJECT TO MANUFACTURER'S WARRANTY		': PARTS - SUBJECT TO MANUFACTURER'S WARRANTY	SUBTOTAL:	\$219.00
Please visit our feedback page at:  www.yaletownplumbing.com/feedback [1]  Fill in the required details from your			LABOUR - 1 YEAR ON NEW UNITS, 30 DAYS ON REPAIR, VOID AFTER 30 DAYS IF MAINTENANCE IS NOT DONE ON NEW UNITS, OR PAYMENT NOT MADE, ABSOLUTELY NO WARRANTY ON CUSTOMER SUPPLIED MATERIALS.  STAT THE LEGAL RATE IS CHARGED ON PAST DUE ACCOUNTS, ACKNOWLEDGEMENT IS HEREBY	GST (5%):	\$10.95
		ls from your		TOTAL:	\$229.95

Thank You!

invoice and tell us how we did.

MADE THAT SERVICES LISTED ABOVE ARE SATISFACTORY COMPLETED AND THAT CHARGES AND MATERIALS LISTED HEREON ARE CORRECT. YALETOWN PLUMBING IS NOT RESPONSIBLE FOR BROKEN, SETTLED, RUSTED, DETERIORATION, OR LEAD PIPES, FIXTURES, CLEAN OUTS AND ANY OTHER DAMAGES RESULTING FROM CLEANING OR REPAIRING EXISTING FIXTURES OR PIPING. TERMS: NET CASH THE AMOUNTS CONTAINED HEREIN ARE FOR LABOUR, MATERIALS AND TRUCK CHARGES. E. & O. E

	2015-10-09
ISTOMER SIGNATURE	DATE
,	STOMER SIGNATURE